

Cemetery Markers (Headstone) Project





Why does this need to be done now?

Many Headstones need repaired so they will last for many more years to come!

At this time an estimate for repairs is \$8,600.00.

If you would like to donate to this project, you may do so by using your collection envelopes. Please write on the envelope **“Headstone Repairs”**. Or you may use a blank envelope and address it to St. Boniface Holy Angles Cemetery.

Thank you for your support with this much needed project.

HPNW Estimate for Repairs		St Boniface Cemetery, Sublin
Marker: R03-02	Name: "Mother" SCHOTT	
Treatment Proposed: grind top of base and reset marker in lime mortar	Priority: low Relevel: no Inclination: Repair: no Reset: yes Estimate for Repair (\$): 150	
Marker: R03-03	Name: Martin DOERFLER	
Treatment Proposed: reset marker in lime mortar and repair cross with epoxy followed by Lithomex infill	Priority: high Relevel: no Inclination: 3 Repair: yes Reset: yes Estimate for Repair (\$): 300	
Marker: R03-04	Name: Maria DORFLER	
Treatment Proposed: repair cross with epoxy followed by Lithomex infill	Priority: low Relevel: no Inclination: 1 Repair: yes Reset: no Estimate for Repair (\$): 200	
Marker: R03-05	Name: Henry VAN HANDEL	
Treatment Proposed: reset shaft in lime mortar	Priority: high Relevel: no Inclination: 2 Repair: no Reset: yes Estimate for Repair (\$): 200	